SPRINT WESTERN OPERATIONS NETWORK OPERATIONS CENTER




FINAL SERVICE DISTUPTION REPORT

DATE OF OUTAGE: 5/16/00	TIME OF OUTAGE: 1:55 PM EDT
DURATION OF OUTAGE: 3:10 (3 hours, 10 minutes)	
GEOGRAPHIC AREA AFFECTED: Warren, Franklin, Andover and Oak Knoll OHIO.	, Cortland, Hartford, Jefferson, Kinsman, New Lyme, Champion
ESTIMATED NUMBER OF CUSTOMERS AFFECTED: 46,12	25
TYPE(S) OF SERVICE AFFECTED: Long distance and Extende affected locations.	ed Area Service (EAS) calls were unavailable to customers in
ESTIMATED NUMBER OF BLOCKED CALLS: 1,073,303 (A	
CAUSE OF INCIDENT: The NEC ITS 600 fiber optic multiplexe	er on the OC-12 system between Warren and
Franklin had failed due to a defective SW-150 card. METHODS USED TO RESTORE SERVICE: The Central Office	ce (CO) technicians contacted NEC Support to trouble-shoot the
hardware fault. The SW-150 card was replaced and the OC-12 syst	em, restored the trunks to service.
STEPS TAKEN TO PREVENT RECURRENCE: A trouble tic hardware design of the SW-150 card and the stand-by circuit design	ket has been opened with NEC (JBAZ-4KDQFN) to investigate the in.
PRIMARY CONTACT NAME:	PHONE:
Amos Anderson	913-791-7372
SECONDARY CONTACT NAME:	PHONE:
Chip Phillips	913-791-4538

c:\winnt\profiles\sprint employee\desktop\nr\wrnoli51600f.cloc REVISED 4/21/99

G. Holfman: 913-624-8199 | FCC, Washington, D.C.: 202-418-2812

00-067



600 New Century Play, New Century, KS 66031 Phone: 918-791-7372/2156 (Hot Line) Fax; 913-791-7361



FCC,	Washington D.C		From:	Sprint LTD NOC-V	Vest: Amos Anderson
202-418-2812		Pages:	ages: 2 with cover sheet		
H -			Date	05/17/00	
: Initial Service Disruption Report		CCit	Greg Hoffman, Spri	nt Corporate Staff	
jent	For Review	Please Con	nment	Please Reply	Please Recycle
	202-	202-418-2812 Initial Service Disrupti	Initial Service Disruption Report	202-418-2812 Pages: Date: Initial Service Disruption Report C(i)	202-418-2812 Pages: 2 with cover sheet

Mr. Kimball,

age in the Warren, OH area yesterday from 1:55 PM EDT to 5:05 PM EDT, octing approximately 46,125 Sprint local telephone customers. This is in pliance with the FCC reporting criteria of an outage affecting 30,000 or more as lines for 30 minutes or longer. The report deadline for initial notification is ad at 72 hours. The Final Service Disruption Report will be filed on or by June 2000. Please contact me if you have any questions regarding this report.

copy of this report has been sent to a member of our Corporate Staff, Mr. Greg man. Thank you very much -

ns Anderson

7.20003711:29AM3 79FCC WASH DC USANETWORK NGT CIR

STERN OPERATIONS
OPERATIONS CENTER

NO.129 P.2/2

⇒ Sprint.

INITIAL SERVICE DISRUPTION REPORT

AGE: 5/16/00	1	TIME OF OUTAGE:	1:55 PM EDT
OUTAGE: 03:10	(3 hours, 10 minutes)		
AREA AFFECTE ak Knoji OHIO,	ED: Warren, Franklin, Andove	er, Cortland, Hartford, J	efferson, Kinsman, New Lyme.
UMBER OF CUS	TOMERS AFFECTED: 46,12	15	
RVICE AFFECT ected locations.	ED: Long distance and Exten	ded Area Service (EAS	S) calls were unavailable to
ABER OF BLO	CKED CALLS: to be provided	on Final Disruption Re	epart
ENT: The NEC	ITS 600 fiber optic multiplexettive SW-150 card.	er on the OC-12 system	between Warren and
TO RESTORE	SERVICE: The Central Office	e (CO) technicians cont	tacted NEC Support to trouble-
TO RESTORE TO FAULT. The SW	SERVICE: The Central Office /-150 card was replaced and t	e (CO) technicians cont ne OC-12 system resto	tacted NEC Support to trouble- pred the trunks to service.
re fault. The SW	SERVICE: The Central Office 1-150 card was replaced and to ECURRENCE: to be provided	he OC-12 system resto	ored the trunks to service.
re fault. The SW	/-150 card was replaced and t	he OC-12 system resto	ored the trunks to service.
re fault. The SW	/-150 card was replaced and t	he OC-12 system resto	ored the trunks to service.
re fault. The SW	/-150 card was replaced and t	he OC-12 system resto	ored the trunks to service.
re fault. The SW	/-150 card was replaced and t	he OC-12 system resto	ored the trunks to service.
re fault. The SW	/-150 card was replaced and t	ne OC-12 system resto	ored the trunks to service.